Subject: Stormwater inspection

Date: Thu, 25 May 2006 11:13:13 -0700

From: "Mendenhall, David N" <dnmendenhall@longfibre.com> Internal

To: "Mitchell George L." <glmitchell@longfibre.com>
CC: "Anderson Michael J." <mjanderson@longfibre.com>

George-

Thank you for sending me a copy of the stormwater inspection report you received from the state inspector. I noted that under "Concerns and Recommendations" he said that you should apply for a "No exposure certificate" from the state. This would remove the obligation of having a stormwater permit and all of the requirements attached to the permit. Have you thought about doing this or have you already done it? The forms are on the web under the Dept. of Ecology. I think you should go ahead and apply for this as it will reduce the amount of time the environmental person will have to spend on stormwater issues at the plant.

Dave

USEPA SF 1256898



STATE OF WASHINGTON DEPARTMENT OF ECOLOGY

Northwest Regional Office • 3190 160th Avenue SE • Bellevue, Washington 98008-5452 • (425) 649-7000

Dear Sir/Madam:

Your facility was recently inspected by an employee of the Department of Ecology. Attached is a copy of the resulting inspection report.

If you have any questions regarding this report, please contact the appropriate inspector at (425) 649-7000.

Sincerely,

Tricia Miller

Permit Coordinator

Water Quality Program

Northwest Regional Office

Liew miller

TM:tm

Attachment



State of Washington Department of Ecology Northwest Regional Office

WADOE Stormwater Compliance Inspection Form Last updated (08/04)

STORMWATER COMPLIANCE INSPECTION REPORT					
Section A: General Data					
Inspection Date NPDES Permit # County 12/22/05 S03000206D King	Receiving Wa		nspector(s) reg Stegman	Fac Type Industrial	
Weather at time of inspection: Overcast					
Discharges to: Surface Water ☑ Ground Water ☐					
Section B: Facility Data					
Name and Location of Facility Inspected		Entry Time		Permit Effective Date	
Longview Fibre Company		10:00 am Exit Time		09/20/02 Permit Expiration Date	
5901 E Marginal Way S		i -	j	<i>'</i>	
Seattle, WA 98134		11:30 am		09/20/07	
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)		Additional	Additional Participants:		
George Mitchell		Mike Anderson, Longview Fibre			
206-762-7171 x250					
Mailing Address of Responsible Official/Title/Phone	and Fax Number.		Yes		
George Mitchell		Samples Taken?			
Longview Fibre Company					
5901 E Marginal Way S		Photos Taken?	\boxtimes	LJ į	
Seattle, WA 98134					
Phone number (206-762-7171 x250) Fax: ()	-				
Contacted?	· .				
⊠ Yes □ No		 			
Section C: Areas Evaluated During inspection (Check those that apply)					
☑ NPDES Permit ☐ Wet & Dry Season Inspection ☑ Operations and Maintenance ☐ Effluent/ Receiving Waters					
☐ Laboratory ☐ Fuel / Chemical Storage ☐ Wheel Wash ☐					
Section D: Summary of Findings/Comments					
CONCERNS AND RECOMMENDATIONS					
Longview Fibre Company meets all conditions listed in S6.C of the industrial stormwater general permit and therefore should be granted a no exposure certificate. To apply for a no exposure certificate see: http://apps.ecy.wa.gov/stormwaterexempt/					
BACKGROUND					
This facility manufactures corrugated and solid fiber boxes. No fueling, vehicle storage, vehicle maintenance or washing are preformed at the facility.					
This facility is covered under the industrial stormwater general permit and has not been inspected previously by the Department of Ecology. The purpose of this inspection is to conduct a compliance inspection per the requirement of the Revised Code of Washington (RCW) 90.48.560 and to provide technical assistance as appropriate.					
Inspection					
I arrived at the facility and met George Mitchell reprints inspection. I then inspected the stormwater catch loading/unloading area.					

Most industrial activity is conducted inside the company's building. The outside area around the building is a public street or owned James Hardie Gypsum next door, with the exception of the truck loading/unloading area.

Stormwater from the truck loading/unloading area is not discharged to surface water, but is collected in a sump, treated and then is used to make box glue. The only other stormwater discharge from the facility is from their roof. I was informed their roof was not made of a material containing zinc.

For questions concerning this inspection report please contact Greg Stegman at (425)-649-7019, gste461@ecy.wa.gov or at the address below.

cc: Greg Stegman, Ecology

Signatures

Reviewed and approved by:

ر ایم

Gregory P. Stegman Stormwater Inspector

Water Quality Program

Date

Donald Seeberger


Unit Supervisor Water Quality Program

Washington State Department of Ecology - NWRO

3190 – 160th Avenue SE Bellevue, WA 98008-5452 Phone: (425) 649-7000

Fax: (425) 649-7098

ANNOUNCED Inspection







5901 East Marginal Way S. • Seattle, WA 98134
P.O. Box 24667 • Seattle, WA 98124
Phone (208) 762-7170 • Fax (205) 767-2442 • www.longviewfibre.com

FAX COVER SHEET

Date: 5-9-06
From: GEORGE MITCHELL
TO: DAVIE MENDENHALL
Company: LUC
Fax Number: 360-575-6110
Total number of pages (including this cover sheet):
Please () do () do not call to confirm receipt of this fax.
If you do not receive all the pages indicated, please contact us at (206) 762-7170
Subject: STORM COMPLIANCE INSPECTION REPORT
Message: attached are the sesults of total wash.
Dest of Ecology storm complaince enspection
report Reend 5-8-06 conducted 12-22-05
1 Xla